University of Alaska Anchorage	Section
	EHS/RMS
ADMINISTRATIVE SERVICES MANUAL	Statement
	37
Policies and Procedures	Page
	1 of 10
Title	Effective Date
TOOL SAFETY	05/30/2012

Purpose Use of tools makes many tasks easier. However, the same tools that assist us can, if improperly used or maintained, can create significant hazards in our work areas. Employees who use tools must be properly trained to use, adjust, store and maintain tools properly. This policy covers hand, electrical, pneumatic, powder driven, and hydraulic tool safety.

Responsibility Management

- Provide correct tools for assigned tasks
- Ensure tools are maintained and stored safely
- Provide employee training
- Provide for equipment repair

Employees

- Follow proper tool safety guidelines
- Report tool deficiencies and malfunctions
- Properly store tools when work is completed

Hazard Controls

Engineering

- Properly designed tools
- Guards & safety devices

Administrative

- Tool sharpening program
- Use of PPE
- Control of tool issue

University of Alaska Anchorage	Section
, ,	EHS/RMS
ADMINISTRATIVE SERVICES MANUAL	Statement
	37
Policies and Procedures	Page
	2 of 10
Title	Effective Date
TOOL SAFETY	05/30/2012

- Employee Training
- Controlled access to equipment and tool areas

General Safety Employees who use hand and power tools and who are exposed to the hazards of falling, flying, abrasive, and splashing objects or exposed to harmful dusts, fumes, mists, vapors, or gases must be provided with the particular personal equipment necessary to protect them from the hazard. Refer to other EHS/RMS applicable policies and procedures that can be found in the EHS/RMS manual found at <u>http://www.uaa.alaska.edu/EHSRMS/policies/polipro.cfm</u>. For clarifications and interpretations, please consult with EHS/RMS at <u>http://www.uaa.alaska.edu/EHSRMS/ehspersonnel.cfm</u>.

Following five basic safety rules can prevent all hazards involved in the use of tools:

- Keep all tools in good condition with regular maintenance.
- Use the right tool for the job.
- Examine each tool for damage before use.
- Operate according to the manufacturer's instructions.
- Provide and use the proper protective equipment.

Hand Tools Hand tools are non-powered. They include anything from axes to wrenches. The greatest hazards posed by hand tools result from misuse and improper maintenance. Some examples include:

- Impact tools such as chisels, wedges, or drift pins are unsafe if they have mushroomed heads. The heads might shatter on impact, sending sharp fragments flying.
- Using a screwdriver as a chisel may cause the tip of the screwdriver to break and fly, hitting the user or other employees.

	University of Alaska Anchorage	Section EHS/RMS
	ADMINISTRATIVE SERVICES MANUAL	Statement
	Policies and Procedures	37 Page
		3 of 10
	Title TOOL SAFETY	Effective Date 05/30/2012
	• If a wooden handle on a tool such as a hammer splintered, or cracked, the head of the tool may the user or another worker.	
	• A wrench must not be used if its jaws are sprun slip.	g, because it might
	Appropriate personal protective equipment, e.g., safet etc., should be worn due to hazards that may be encou portable power tools and hand tools.	
	Floors shall be kept as clean and dry as possible to prevent accidental slips with or around dangerous hand tools.	
	Around flammable substances, sparks produced by iro tools can be a dangerous ignition source. Where this h resistant tools made from brass, plastic, aluminum, or for safety.	nazard exists, spark-
Power Tools	Power tools can be hazardous when improperly used. types of power tools, based on the power source they pneumatic, liquid fuel, hydraulic, and powder-actuate	use: electric,
	Power tool users should observe the following general precautions:	
	• Never carry a tool by the cord or hose.	
	• Never yank the cord or the hose to disconnect it from the receptacle.	
	• Keep cords and hoses away from heat, oil, and sharp edges.	
	• Disconnect tools when not in use, before servicing, and when changing accessories such as blades, bits, and cutters.	
	• All observers should be kept at a safe distance awa area.	ay from the work
	• Secure work with clamps or a vise, freeing both ha tool.	ands to operate the

University of Alaska Anchorage	Section
	EHS/RMS
ADMINISTRATIVE SERVICES MANUAL	Statement
	37
Policies and Procedures	Page
	4 of 10
Title	Effective Date
TOOL SAFETY	05/30/2012

- Avoid accidental startings. The worker should not hold a finger on the switch button while carrying a plugged-in tool.
- Tools should be maintained with care. They should be kept sharp and clean for the best performance. Follow instructions in the user's manual for lubricating and changing accessories.
- Be sure to keep good footing and maintain good balance.
- The proper apparel should be worn. Loose clothing, ties, or jewelry can become caught in moving parts.
- All portable electric tools that are damaged shall be removed from use and tagged "Do Not Use."

Guards Hazardous moving parts of a power tool need to be safeguarded. For example, belts, gears, shafts, pulleys, sprockets, spindles, drums, fly wheels, chains, or other reciprocating, rotating, or moving parts of equipment must be guarded.

Guards, as necessary, should be provided to protect the operator and others from the following:

- point of operation,
- in-running nip points,
- rotating parts, and
- flying chips and sparks.

Safety guards must never be removed when a tool is being used. For example, portable circular saws must be equipped with guards. An upper guard must cover the entire blade of the saw. A retractable lower guard must cover the teeth of the saw, except when it makes contact with the work material. The lower guard must automatically return to the covering position when the tool is withdrawn from the work.

Safety Switches The following hand-held powered tools are to be equipped with a momentary contact "on-off" control switch: drills, tappers, fastener

University of Alaska Anchorage	Section
	EHS/RMS
ADMINISTRATIVE SERVICES MANUAL	Statement
	37
Policies and Procedures	Page
	5 of 10
Title	Effective Date
TOOL SAFETY	05/30/2012

drivers, horizontal, vertical and angle grinders with wheels larger than 2 inches in diameter, disc and belt sanders, reciprocating saws, saber saws, and other similar tools. These tools also may be equipped with a lock-on control provided that turnoff can be accomplished by a single motion of the same finger or fingers that turn it on.

The following hand-held powered tools may be equipped with only a positive "on-off" control switch: platen sanders, disc sanders with discs 2 inches or less in diameter; grinders with wheels 2 inches or less in diameter; routers, planers, laminate trimmers, nibblers, shears, scroll saws and jigsaws with blade shanks ¹/₄-inch wide or less.

Other hand-held powered tools such as circular saws having a blade diameter greater than 2 inches, chain saws, and percussion tools without positive accessory holding means must be equipped with a constant pressure switch that will shut off the power when the pressure is released.

Electrical Safety The chief hazards of electric-powered tools are burns and slight shocks which can lead to injuries or even heart failure. Under certain conditions, even a small amount of current can result in severe injury and eventual death. A shock also can cause the user to fall off a ladder or other elevated work surface.

To protect the user from shock, tools must either have a three-wire cord with ground and be grounded, be double insulated, or be powered by a low-voltage isolation transformer. Three-wire cords contain two currentcarrying conductors and a grounding conductor. One end of the grounding conductor connects to the tool's metal housing. The other end is grounded through a prong on the plug. Anytime an adapter is used to accommodate a two-hole receptacle, the adapter wire must be attached to a known ground. The third prong should never be removed from the plug.

Double insulation is more convenient. The user and the tools are protected in two ways: by normal insulation on the wires inside, and by a

University of Alaska Anchorage	Section
, , ,	EHS/RMS
ADMINISTRATIVE SERVICES MANUAL	Statement
	37
Policies and Procedures	Page
	6 of 10
Title	Effective Date
TOOL SAFETY	05/30/2012

housing that cannot conduct electricity to the operator in the event of a malfunction.

Additional general electrical safety precautions should be taken:

- Gloves and safety footwear are recommended during use of electric tools.
- Electric tools should be operated within their design limitations.
- When not in use, tools should be stored in a dry place.
- Electric tools should not be used in damp or wet locations.
- Work areas should be well lit.
- *Abrasive Wheels* Powered abrasive grinding, cutting, polishing, and wire buffing wheels create special safety problems because they may throw off flying fragments.

Before an abrasive wheel is mounted, it should be inspected closely and sound- or ring-tested to be sure that it is free from cracks or defects. To test, wheels should be tapped gently with a light non-metallic instrument. If they sound cracked or dead, they could fly apart in operation and so must not be used. A sound and undamaged wheel will give a clear metallic tone or "ring."

To prevent the wheel from cracking, the user should be sure it fits freely on the spindle. The spindle nut must be tightened enough to hold the wheel in place, without distorting the flange. Follow the manufacturer's recommendations. Care must be taken to assure that the spindle wheel will not exceed the abrasive wheel specifications.

Due to the possibility of a wheel disintegrating (exploding) during startup, the employee should never stand directly in front of the wheel as it accelerates to full operating speed.

University of Alaska Anchorage	Section
	EHS/RMS
ADMINISTRATIVE SERVICES MANUAL	Statement
	37
Policies and Procedures	Page
	7 of 10
Title	Effective Date
TOOL SAFETY	05/30/2012

Portable grinding tools need to be equipped with safety guards to protect workers not only from the moving wheel surface, but also from flying fragments in case of breakage.

Additional portable grinder safety precautions are as follow:

- Always use eye protection.
- Turn off the power when not in use.
- Never clamp a hand-held grinder in a vise.
- PneumaticsPneumatic tools are powered by compressed air and include chippers,
drills, hammers, and sanders. There are several dangers encountered in
the use of pneumatic tools. The main one is the danger of getting hit by
one of the tool's attachments or by some kind of fastener the worker is
using with the tool. Eye protection is required and face protection is
recommended for employees working with pneumatic tools. Working
with noisy tools such as jackhammers or impact wrenches requires
proper, effective use of hearing protection.

When using pneumatic tools, employees shall check to see that they are fastened securely to the hose to prevent them from becoming disconnected. A short wire or positive locking device attaching the air hose to the tool will serve as an added safeguard.

A safety clip or retainer must be installed to prevent attachments, such as chisels on a chipping hammer, from being unintentionally shot from the barrel.

Screens must be set up to protect nearby workers from being struck by flying fragments around chippers, riveting guns, staplers, or air drills.

Compressed air guns should never be pointed toward anyone. Users should never "dead-end" it against themselves or anyone else.

University of Alaska Anchorage	Section
	EHS/RMS
ADMINISTRATIVE SERVICES MANUAL	Statement
	37
Policies and Procedures	Page
	8 of 10
Title	Effective Date
TOOL SAFETY	05/30/2012

- *Powder-Actuated* Powder-actuated tools operate like a loaded gun and should be treated with the same respect and precautions. In fact, they are so dangerous that only specially trained employees must operate them.
 - These tools should not be used in an explosive or flammable atmosphere.
 - Before using the tool, the worker should inspect it to determine that it is clean, that all moving parts operate freely, and that the barrel is free from obstructions.
 - The tool should never be pointed at anybody.
 - The tool should not be loaded unless it is to be used immediately. A loaded tool should not be left unattended, especially where it would be available to unauthorized persons.
 - Hands should be kept clear of the barrel end. To prevent the tool from firing accidentally, two separate motions are required for firing: one to bring the tool into position, and another to pull the trigger. The tools must not be able to operate until they are pressed against the work surface with a force of at least 5 pounds greater than the total weight of the tool.

If a powder-actuated tool misfires, the employee should wait at least 30 seconds, then try firing it again. If it still will not fire, the user should wait another 30 seconds so that the faulty cartridge is less likely to explode, than carefully remove the load. The bad cartridge should be put in water.

Suitable eye and face protection are essential when using a powderactuated tool.

The muzzle end of the tool must have a protective shield or guard centered perpendicularly on the barrel to confine any flying fragments or particles that might otherwise create a hazard when the tool is fired. The tool must be designed so that it will not fire unless it has this kind of safety device.

University of Alaska Anchorage	Section
	EHS/RMS
ADMINISTRATIVE SERVICES MANUAL	Statement
	37
Policies and Procedures	Page
	9 of 10
Title	Effective Date
TOOL SAFETY	05/30/2012

All powder-actuated tools must be designed for varying powder charges so that the user can select a powder level necessary to do the work without excessive force.

If the tool develops a defect during use it should be tagged and taken out of service immediately until it is properly repaired.

When using powder-actuated tools to apply fasteners, there are some precautions to consider. Fasteners must not be fired into material that would let them pass through to the other side. The fastener must not be driven into materials like brick or concrete any closer than 3 inches to an edge or corner. In steel, the fastener must not come any closer than onehalf inch from a corner or edge. Fasteners must not be driven into very hard or brittle materials, which might chip or splatter, or make the fastener ricochet.

An alignment guide must be used when shooting a fastener into an existing hole. A fastener must not be driven into a spalled area caused by an unsatisfactory fastening.

Hydraulics The fluid used in hydraulic power tools must be an approved fireresistant fluid and must retain its operating characteristics at the most extreme temperatures to which it will be exposed. The manufacturer's recommended safe operating pressure for hoses, valves, pipes, filters, and other fittings must not be exceeded.

> All jacks - lever and ratchet jacks, screw jacks, and hydraulic jacks must have a device that stops them from jacking up too high. Also, the manufacturer's load limit must be permanently marked in a prominent place on the jack and should not be exceeded.

> A jack should never be used to support a lifted load. Once the load has been lifted, it must immediately be blocked up.

Use wooden blocking under the base if necessary to make the jack level and secure. If the lift surface is metal, place a 1-inch-thick hardwood block or equivalent between it and the metal jack head to reduce the danger of slippage.

To set up a jack, make certain of the following:

University of Alaska Anchorage	Section EHS/RMS
ADMINISTRATIVE SERVICES MANUAL	Statement 37
Policies and Procedures	Page 10 of 10
Title	Effective Date
TOOL SAFETY	05/30/2012

- the base rests on a firm level surface,
- the jack is correctly centered,
- the jack head bears against a level surface, and
- the lift force is applied evenly.

Proper maintenance of jacks is essential for safety. All jacks must be inspected before each use and lubricated regularly. If a jack is subjected to an abnormal load or shock, it should be thoroughly examined to make sure it has not been damaged.

Hydraulic jacks exposed to freezing temperatures must be filled with adequate antifreeze liquid.